

## Technical Bulletin #8

### Performance Tip

#### *Nuisance Pilot Outages with Sterling DV Model 8531 in Minimum Vent Situations*

**Publication Date:** May 24, 2001

**Re:** Sterling "G" Direct Vent (Model 8531)

**Description:** When installing the Sterling Direct Vent Model 8531 in minimum horizontal venting situations, you must take note of high, or erratic wind areas. If the termination cap is in an area subject to high or erratic winds, a short vertical rise on the inside of the home or a 14" snorkel on the outside is recommended to prevent nuisance pilot outages.

